

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave.St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:**Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-000420**Date Inspected:** 31-Aug-2007**Project Name:** SAS Superstructure**OSM Arrival Time:** 630**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1530**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China


CWI Name:	N/A	CWI Present:	Yes	No
Inspected CWI report:	Yes	No	N/A	Rod Oven in Use: Yes No N/A
Electrode to specification:	Yes	No	N/A	Weld Procedures Followed: Yes No N/A
Qualified Welders:	Yes	No	N/A	Verified Joint Fit-up: Yes No N/A
Approved Drawings:	Yes	No	N/A	Approved WPS: Yes No N/A
				Delayed / Cancelled: Yes No N/A
Bridge No:	34-0006	Component:	Receive Steel Plate	

Summary of Items Observed:

Caltrans Quality Assurance (QA) Inspector Charlie Franco was present at the time requested to observe material received in the ZPMC yard today. There were a total of 81 out of a total of 91 plates from Batch Number 10 received for production with thicknesses ranging from 8 millimeters to 20 millimeters. The plates were ASTM A709M-345F2-X, ASTM A709M-345T2-X and ASTM A709M-345T2-X-S material and were accompanied with material test reports (MTR's). The MTRs could not be reviewed on the day the plates were observed for their general condition and markings but will be reviewed at the earliest opportunity. The QA Inspector assigned Caltrans Lot Number B75-060-07 to the 81 steel plates received today 08-31-07. The following photograph provides additional detail.

WELDING INSPECTION REPORT

(Continued Page 2 of 2)



Summary of Conversations:

ZPMC QA Representative Shen Xue Jun informed the QA Inspector that he would have someone contact the QA Inspector at 0730 tomorrow morning to receive the steel plates from the balance of Batch Number 10 and receive Batch Number 11.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Mazen Wahbeh, (818) 292-0659, who represents the Office of Structural Materials for your project.

Inspected By: Franco,Charlie

Quality Assurance Inspector

Reviewed By: Cuellar,Robert

QA Reviewer